
MARION COUNTY SURVEYOR'S OFFICE

DEBRA S. JENKINS MARION COUNTY SURVEYOR SECTION CORNER RECORD SEC. $35\,\mathrm{TWN}$. $15_{\mathrm{N}}\,\mathrm{RNG}$. 2_{E}

BRYAN F. CATLIN, PLS TECHNICAL SUPERVISOR



Corner originally set as a post in 1820 by Wm. B. Laughlin with the following witnesses: 14" beech bearing N 7 E 10 links and an 18" dogwood bearing N 20 W 12 links. (Marion County Atlas p. 2) A survey by D.B. Hasbrook on February 15, 1886 indicates a rock set with no witnesses. (Decatur Legal Book p. 1) Corner referenced by Monroe on 5/11/1961 and called a half inch pipe. Corner referenced by Fortner on 8/23/74 and called a RR spike. Corner referenced by Kiste on 8/11/93 and called a RR spike. Corner referenced by Wilcoxen on 5/29/1998 and called an airport authority disk in steel box. Corner referenced by Wilcoxen on 6/16/2003 and called an airport authority disk in steel box. Corner referenced by Wilcoxen on 5/21/09 and called an airport authority disk in steel box.

REF.	DISTANCE	DESCRIPTION
1.	108.55'	PK nail W PwP #17-653 A 15" up
2.	45.63'	PK nail w/survey marker tag NW light pole #577-653 A 12" up
3.	68.16'	Mag nail w/brass washer S PwP #16-653 B 20" up
4.	85.63'	Mag nail w/brass washer W PwP #561-653 B 18" up
5.	52.03'	SE corner of brick 3940 Kollman Rd